

1 Phase

2 Pole

R 100

TECHNICAL DATA

TYPE	60 Hz - 3600 r.p.m.		50 Hz - 3000 r.p.m.		Weight (kg)
	POWER (kVA)	cosφ= 1 (%)	POWER (kVA)	cosφ= 1 (%)	
R12 SAS	2.1	68	1.7	67	14.5
R12 SBS	2.7	73	2.2	71	15.5
R12 SCH	3.2	75	2.6	74	16.3
R12 SCS	3.7	76	3.0	75	16.6

